

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2017

Submitted Date:

03/31/2017

Document Number:

666803067**FIELD INSPECTION FORM**
 Loc ID 335379 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263512	WELL	PR	04/05/2005	GW	045-08133	BRYNILDSON 13C-20-692	PR
276580	WELL	PR	03/13/2009	GW	045-10488	BRYNILDSON 13B-20-692	PR
276581	WELL	PR	05/31/2005	GW	045-10487	BRYNILDSON 12A-20-692	PR
276741	WELL	PR	03/01/2009	GW	045-10513	BRYNILDSON 13D-20-692	PR
297757	WELL	PR	03/16/2009	GW	045-16952	BRYNILDSON 12C-20-692	PR
297758	WELL	PR	03/06/2009	GW	045-16953	BRYNILDSON 22A-20-692	PR
297759	WELL	PR	03/01/2009	GW	045-16954	BRYNILDSON 22B-20-692	PR
297760	WELL	PR	03/01/2009	GW	045-16955	BRYNILDSON 22C-20-692	PR
297761	WELL	PR	03/11/2009	GW	045-16956	BRYNILDSON 23B-20-692	PR
297762	WELL	PR	03/05/2009	GW	045-16957	BRYNILDSON 23C-20-692	PR
297763	WELL	PR	02/25/2009	GW	045-16958	BRYNILDSON 23D-20-692	PR
297764	WELL	PR	03/10/2009	GW	045-16959	BRYNILDSON 12B-20-692	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

2

Comment:

Chemical units at wellhead

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

12

Comment:

Corrective Action:

Date:

Type: Plunger Lift

12

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLS	STEEL AST		39.510971,-107.696943

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	263512	Type:	WELL	API Number:	045-08133	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276580	Type:	WELL	API Number:	045-10488	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276581	Type:	WELL	API Number:	045-10487	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276741	Type:	WELL	API Number:	045-10513	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297757	Type:	WELL	API Number:	045-16952	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297758	Type:	WELL	API Number:	045-16953	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297759	Type:	WELL	API Number:	045-16954	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297760	Type:	WELL	API Number:	045-16955	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	297761	Type:	WELL	API Number:	045-16956	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	297762	Type:	WELL	API Number:	045-16957	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	297763	Type:	WELL	API Number:	045-16958	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	297764	Type:	WELL	API Number:	045-16959	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Rip Rap	Pass					
		Gravel	Pass			
Ditches	Pass					
Berms	Pass					
Check Dams	Pass					
Sediment Traps	Pass					
		Culverts	Pass			
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248081	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113256