

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/29/2017

Submitted Date:

03/31/2017

Document Number:

666803070**FIELD INSPECTION FORM**

Loc ID 335454 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268492	WELL	PR	07/12/2012	GW	045-09266	EM 30-7 (B30NE)	PR
268493	WELL	PR	07/12/2012	GW	045-09267	EM 30-2 (B30NE)	PR
272098	WELL	SI	01/01/2017	GW	045-10023	BRYNILDSON 30-3 (B30NE)	SI
272107	WELL	PR	07/12/2012	GW	045-10025	BRYNILDSON 30-6 (B30NE)	PR
273518	WELL	PR	01/18/2005	GW	045-10257	BRYNILDSON 30-8 (B30NE)	PR
273554	WELL	PR	08/01/2012	GW	045-10259	BRYNILDSON 30-1 (B30NE)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 6

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 6

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,

Comment: Centralized battery

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		39.501829,-107.707620	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: 268492	Type: WELL	API Number: 045-09266	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: blue;">Plunger lift</span>				
Corrective Action:		Date:		
Facility ID: 268493	Type: WELL	API Number: 045-09267	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: blue;">Plunger lift</span>				
Corrective Action:		Date:		
Facility ID: 272098	Type: WELL	API Number: 045-10023	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: <span style="color: blue;">Last production numbers posted Oct 2016</span>				
Corrective Action:		Date:		
Facility ID: 272107	Type: WELL	API Number: 045-10025	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: blue;">Plunger lift</span>				
Corrective Action:		Date:		
Facility ID: 273518	Type: WELL	API Number: 045-10257	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: blue;">Plunger lift</span>				
Corrective Action:		Date:		
Facility ID: 273554	Type: WELL	API Number: 045-10259	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: blue;">Plunger lift</span>				
Corrective Action:		Date:		

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
		Ditches	Pass			
Sediment Traps	Pass					
		Culverts	Pass			
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248084	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113259">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113259</a>