

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

669600033**FIELD INSPECTION FORM**Loc ID 306755 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:                     **Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263013	WELL	PR	03/15/2002	GW	067-08704	TINKER FEDERAL 2	PR

**General Comment:**

[See link at end of report for path to downloadable pictures.](#) [Inspection report contains comment.](#) [See Signs/Marker section for additional information.](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Old wellhead sign was left on location when new sign was installed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER			,
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

**Paint**

Condition	Adequate	
Other (Content)	<input type="text"/>	
Other (Capacity)	21 BBLS	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Corrective action completed.			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

**Venting:**

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

**Flaring:**

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 263013    Type: WELL    API Number: 067-08704    Status: PR    Insp. Status: PR

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248910	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114274">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114274</a>
669600107	Weeds and grass removed from inside containment 1.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114247">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114247</a>
669600108	Weeds and grass removed from inside containment 2.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114248">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114248</a>
669600110	Old wellhead sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114249">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114249</a>
669600111	Location overview.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114250">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114250</a>