

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

669600034**FIELD INSPECTION FORM**Loc ID 306917 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277748	WELL	PR	04/15/2010	GW	067-09045	FEDERAL 14-01 2	PR

General Comment:[See link at end of report for path to downloadable pictures.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Corrective action completed. Additional monitoring maybe required as spring growth is emerging and may need treatment to avoid growth around production equipment.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV STEEL		,	
Comment:						
Corrective Action:						Date: <input type="text"/>

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Corrective action completed. Additional monitoring maybe required as spring growth is emerging and may need treatment to avoid growth on containment berms.			
Corrective Action:				Date: <input type="text"/>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: <input type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 277748 Type: WELL API Number: 067-09045 Status: PR Insp. Status: PR

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248911	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114275
669600113	Location overview.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114251
669600119	Weeds and grass removed from inside production equipment fencing.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114252
669600121	Weeds and grass removed from inside pump jack fencing.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114253
669600123	Emerging weeds and grass around and on berms.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114254