

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

669600036**FIELD INSPECTION FORM**Loc ID 325909 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215550	WELL	PR	08/12/2005	GW	067-07155	KAIME FEDERAL 1	PR

General Comment:[See link at end of report for path to downloadable pictures. Inspection report contains additional comments. See Signs/Marker section for additional details.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Corrective action completed. Tank has been relabeled but labels are not readable from outside containment ring. This issue has previously been identified on other locations and is currently in work towards resolution. Labels must be placed in conspicuous place to comply with Rule 210.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Corrective action completed.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215550 Type: WELL API Number: 067-07155 Status: PR Insp. Status: PR

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248913	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114277
669600137	Labels on top of tank and not visible from outside containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114257
669600138	Location overview where post had been before removal.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114258
669600139	Repaired animal burrow at front of tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114259
669600140	Repaired animal burrow from inside containment ring.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114260
669600142	Removed grass and weeds from inside containment ring.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114261