

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2017

Submitted Date:

04/07/2017

Document Number:

674005006**FIELD INSPECTION FORM**

Loc ID 336155 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 289783 | WELL | PR | 08/01/2015 | OW | 123-24914 | CARMA 14-35 | PR |
| 290565 | WELL | PR | 11/14/2008 | OW | 123-25141 | CARMA 34-35 | PR |
| 290676 | WELL | PR | 08/01/2015 | OW | 123-25189 | CARMA 23-35 | PR |
| 291195 | WELL | PR | 10/23/2008 | OW | 123-25988 | CARMA 35-35 | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Chainlink | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------------------|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | Shared with API 05-123-38632 | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | |
|--|-------------------|------------------------------|---|
| Facility ID: <u>289783</u> | Type: <u>WELL</u> | API Number: <u>123-24914</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| <u>Producing Well</u> | | | |
| Comment: <u>PR</u> | | | |
| Corrective Action: | | Date: | |
| <u>BradenHead</u> | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>290565</u> | Type: <u>WELL</u> | API Number: <u>123-25141</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| <u>Producing Well</u> | | | |
| Comment: <u>PR</u> | | | |
| Corrective Action: | | Date: | |
| <u>BradenHead</u> | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>290676</u> | Type: <u>WELL</u> | API Number: <u>123-25189</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| <u>Producing Well</u> | | | |
| Comment: <u>PR</u> | | | |
| Corrective Action: | | Date: | |
| <u>BradenHead</u> | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>291195</u> | Type: <u>WELL</u> | API Number: <u>123-25988</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| <u>Producing Well</u> | | | |
| Comment: <u>PR</u> | | | |
| Corrective Action: | | Date: | |
| <u>BradenHead</u> | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | | | |
| Corrective Action: | | Date: | |
| <u>COGCC Comments</u> | | | |
| Comment | User | Date | |
| <u>Routine inspection. Photos with battery inspection with well api 05-123-38632</u> | <u>carlilec</u> | <u>04/07/2017</u> | |