

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/30/2017

Submitted Date:

04/03/2017

Document Number:

673404377**FIELD INSPECTION FORM**
 Loc ID 414127 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
James, Michael	405-519-6634	mjames@sandridgeenergy.com	
Laird, Spence		slaird@sandridgeenergy.com	
Hewins, Grant		ghewins@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413066	WELL	PR	12/25/2010	OW	057-06501	HEBRON 1-18H	PR
413067	WELL	PR	12/25/2010	OW	057-06502	HEBRON 5-18H	PR
439660	WELL	PR	08/11/2016	LO	057-06536	Hebron 01-18HR	PR
444867	WELL	PR	08/11/2016		057-06540	Hebron 0780 02-18H	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Not all containers labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 05/03/2017

Emergency Contact Number:

Comment: 405-429-5974

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Broken portapotty sitting in snowmelt.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLS	STEEL AST		40.584030,-106.415160

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			Inadequate

Comment:	Berm is low on northeast end.
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Date: 05/03/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLS	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			Inadequate

Comment:	Berm is low on northeast end.
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Date: 05/03/2017

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:



Inspected FacilitiesFacility ID: 413066 Type: WELL API Number: 057-06501 Status: PR Insp. Status: PR**Producing Well**Comment: Pumping

Corrective Action:

Date:

Facility ID: 413067 Type: WELL API Number: 057-06502 Status: PR Insp. Status: PR**Producing Well**Comment: Pumping

Corrective Action:

Date:

Facility ID: 439660 Type: WELL API Number: 057-06536 Status: PR Insp. Status: PR**Producing Well**Comment: Pumping

Corrective Action:

Date:

Facility ID: 444867 Type: WELL API Number: 057-06540 Status: PR Insp. Status: PR**Producing Well**Comment: Pumping

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	
Compaction	Pass					
Gravel	Pass					
Berms	Pass					

Comment: [No secondary containment for unlabeled containers sitting in snowmelt.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.](#)

Date: 05/03/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401251282	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116080
673404382	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116010