

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal Picket		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292038 Type: WELL API Number: 123-26215 Status: SI Insp. Status: SI

Producing Well

Comment:

Corrective Action:

Date:

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder:

Comment:

Corrective Action:

Date:

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: 40.193340 Long: -104.965910

Wind: Steady Speed: 20 (mph) Direction From: South Weather: Clear Temperature: 49 (F)

Assisting Staff: _____ Camera #: _____

Visible Smoke Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
12:10	PM	12:15	PM	Wellhead(s)

Comment: No emissions noted.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine optical gas imaging inspection of wellhead.</u>	carlilec	04/10/2017