

Inspection Photos
Location Name: Iles Dome Unit 37
API: 05-081-05090



Photo 1. View at entrance to location facing southeast.

Inspection Photos
Location Name: Iles Dome Unit 37
API: 05-081-05090



Photo 2. Ongoing leak at wellhead. Fresh oil and stained soil. 4/5/2017 Inspection



Photo 3. Ongoing leak at wellhead. Fresh oil and stained soil. 12/6/2016 Inspection