

Reference Area Photographs

Inspection Conducted on March 08,, 2017

SG Interests

McIntyre E&P Waste Management Facility

Centralized Facility #421066

Pit #3 Facility ID # 418791

Pit #4 Facility ID # 418790

Location ID #423374



McIntyre E&P Waste Management Facility



Lower Pit (Looking West)



Upper Pit (Looking Norwest)

McIntyre E&P Waste Management Facility



Upper Pit (looking Northwest). Netting in good general conditions. Color flags.



Upper Pit (looking East). Produced Water Discharge Manifold

McIntyre E&P Waste Management Facility



Access/Emergency road around the upper pit (looking Northeast)



Upper Pit (looking Southeast)

McIntyre E&P Waste Management Facility



Lower Pit. Looking south. Manifold at the center of the photo.




Lower Pit. Looking southeast. Access/service road continues around lower pit (and around upper pit as well).

McIntyre E&P Waste Management Facility



Lower Pit. Permanently Installed Produced Water discharge Manifold



Lower Pit. Discharge piping
Some observed damage to the netting

McIntyre E&P Waste Management Facility



Lower Pit. Looking south. Access/service road and storm water management (drainage and retention pond on the down gradient side (far south on the photo).



One of the three monitoring wells. All three on the south/down-gradient side of lower pit.
Note: There is a MW up-gradient (north) of the upper pit.

All four are regularly gauged and sampled