

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2017

Submitted Date:

04/04/2017

Document Number:

674703799**FIELD INSPECTION FORM**

Loc ID 335800 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------------|--------------|------------------------------|---|
| Inspections, General | 970-285-2665 | cogcc.inspections@encana.com | EnCana Inspection email |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 277115 | WELL | PR | 01/05/2006 | GW | 045-10604 | N.PARACHUTE WF14D A15 596 | PR |
| 428147 | PIT | AC | 03/12/2012 | | - | WEST FORK A-15 596 | AC |

General Comment:

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|-------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | PIT | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------|-----|--|-----------------|
| Type: Bird Protectors | # 1 | | corrective date |
| Comment: | | | |

| | | | |
|-----------------------------------|---------------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chemical container at gas meter shed. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | | | | | | |
|----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Inspected Facilities | | | | | | | | | |
| Facility ID: | 277115 | Type: | WELL | API Number: | 045-10604 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 428147 | Type: | PIT | API Number: | - | Status: | AC | Insp. Status: | AC |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | | | | | |
| Ditches | Pass | | | | | |
| Gravel | Pass | | | | | |
| | | Compaction | Pass | | | |
| | | Culverts | Pass | | | |
| | | Ditches | Pass | | | |
| Check Dams | Pass | | | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| Seeding | Pass | | | | | |
| Berms | Pass | | | | | |
| | | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Lined: YES Pit ID: 428147 Lat: 39.621792 Long: -108.148903

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition: Adequate

Comment: Corrective Action Date: g**Fencing:**

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment: Corrective Action Date: **Netting:**

Netting Type: Fence/Net Combo Netting Condition: Good

Comment: Corrective Action Date:

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: Corrective Action Date:

| | | |
|-------------|-----------------|----------|
| Monitoring: | Monitoring Type | Comment` |
| | Chain | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 401253216 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118201 |
| 674703800 | A15 596 photo from entrance | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118191 |