

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2017

Submitted Date:

04/06/2017

Document Number:

674901578**FIELD INSPECTION FORM**

|        |                 |                    |  |
|--------|-----------------|--------------------|--|
| Loc ID | Inspector Name: | On-Site Inspection | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>5 Number of Comments<br>0 Number of Corrective Actions<br><input type="checkbox"/> Corrective Action Response Requested |
|        | Hughes, Jim     | 2A Doc Num:        |  |

**Operator Information:**OGCC Operator Number: 76104Name of Operator: SAMSON RESOURCES COMPANYAddress: 15 E 5TH ST STE 1000City: TULSA State: OK Zip: 74103**Contact Information:**

| Contact Name      | Phone        | Email                     | Comment            |
|-------------------|--------------|---------------------------|--------------------|
| Fischer, Alex     |              | alex.fischer@state.co.us  |                    |
| Ikenouye, Teri    |              | teri.ikenouye@state.co.us |                    |
| Blanchard, Johnna | 970-884-5085 | jblanchard@samson.com     | All SW Inspections |

**General Comment:**

On March 24, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Samson Resources Pit Facility ID #115588. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115588 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.

**Location**Overall Good: ☐

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             | Location sign reads 067-09243, which is the API number for the Red Willow Ute 33-8-29 #6. |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType:  Lined:  Pit ID: 115588 Lat: 37.073230 Long: -107.715963Reference Point:  Other:  Length:  Width: **Lining:**Liner Type:  Liner Condition: Comment: Location inspection conducted to determine physical existence of pit facility ID #115588.Corrective Action: Date: c**Fencing:**Fencing Type:  Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type:  Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present:  Oil Accumulation:  2+ feet Freeboard: Comment: Corrective Action: Date: **COGCC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| On March 24, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Samson Resources Pit Facility ID #115588. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115588 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits. During this field inspection, it was noted that the location sign has the incorrect API # listed. The sign reads 067-09243 which is for the Red Willow Ute 33-8-29 #6. | hughesj | 04/06/2017 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                              | URL   |
|--------------|--|---|
| 401252665    | INSPECTION SUBMITTED                     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117503">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117503</a> |
| 674901579    | Incorrect API # listed on location sign. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117499</a> |
| 674901580    | Location photo looking NE.               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117500</a> |

|           |                            |   |
|-----------|----------------------------|---|
| 674901581 | Location photo looking SW. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117501</a> |
|-----------|----------------------------|---|

