

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2017

Submitted Date:

04/06/2017

Document Number:

674901582

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 77330  
 Name of Operator: SG INTERESTS I LTD  
 Address: 100 WAUGH DR SUITE 400  
 City: HOUSTON State: TX Zip: 77007

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspections@sginterests.com	<a href="#">All Inspections</a>
Fischer, Alex		alex.fischer@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	

**General Comment:**

On March 24, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #105453. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #105453 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: 105453      Lat: 37.080300      Long: -107.688772

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: [Location inspection conducted to determine physical existence of pit facility ID #105453.](#)

Corrective Action

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">On March 24, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #105453. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #105453 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits. Document review indicates that a drilling reserve pit did exist at one time.</a>	hughesj	04/06/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401252742	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117579">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117579</a>
674901583	Location photo looking E.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117575">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117575</a>
674901584	Location photo looking S.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117576">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117576</a>