

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2017

Submitted Date:

04/07/2017

Document Number:

666803086**FIELD INSPECTION FORM**
 Loc ID 335433 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|------------------------------------|-----------------------------------|
| , Inspections | | COGCCInspectionReports@terraep.com | Field Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 272558 | WELL | PR | 11/28/2004 | GW | 045-10099 | FEDERAL RWF 323-19 | PR |
| 272559 | WELL | PR | 12/03/2004 | GW | 045-10098 | FEDERAL RWF 23-19 | PR |
| 272788 | WELL | PR | 12/14/2004 | GW | 045-10158 | FEDERAL RWF 423-19 | PR |
| 272789 | WELL | PR | 12/06/2004 | GW | 045-10157 | FEDERAL RWF 523-19 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

4

Comment: Corrective Action: Date:

Type: Plunger Lift

4

Comment: Corrective Action: Date:

Type: Emission Control Device

0

Comment: [Disconnected](#)Corrective Action: Date: **Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------|----------|-----------|---------|----------------------------|
| PRODUCED WATER | 1 | 300 BBLS | STEEL AST | | 39.507376,-107.932929 |
| Comment: | <input type="text"/> | | | | |
| Corrective Action: | <input type="text"/> | | | | Date: <input type="text"/> |

Paint

Condition: Adequate

Other (Content) Other (Capacity) Other (Type) **Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------|---------------------|---------------------|----------------------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | <input type="text"/> | | | |
| Corrective Action: | <input type="text"/> | | | Date: <input type="text"/> |

Venting:

Yes/No NO

Comment:

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 272558 | Type: | WELL | API Number: | 045-10099 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 272559 | Type: | WELL | API Number: | 045-10098 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 272788 | Type: | WELL | API Number: | 045-10158 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 272789 | Type: | WELL | API Number: | 045-10157 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| Environmental | |
|------------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): YES | |
| Comment: | Disconnected |
| Pilot: OFF | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | | | | | |
| Berms | Pass | | | | | |
| | | Ditches | Pass | | | |
| | | Gravel | Pass | | | |
| Sediment Traps | Pass | | | | | |
| Ditches | Pass | | | | | |
| | | Culverts | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401253640 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118765 |