

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2017

Submitted Date:

04/07/2017

Document Number:

666803087**FIELD INSPECTION FORM**

Loc ID 335396 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|------------------------------------|-----------------------------------|
| , Inspections | | COGCCInspectionReports@terraep.com | Field Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 276956 | WELL | PR | 08/29/2005 | OW | 045-10575 | FEDERAL RWF 424-19 | PR |
| 276958 | WELL | PR | 09/21/2005 | OW | 045-10574 | FEDERAL RWF 324-19 | PR |
| 276961 | WELL | PR | 09/16/2005 | OW | 045-10573 | FEDERAL RWF 24-19 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

0

Comment: Corrective Action: Date:

Type: Plunger Lift

3

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

3

Comment: Corrective Action: Date: **Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------------------------------------|---|----------|-----------|---------|----------------------------|
| CONDENSATE | 1 | 200 BBLS | STEEL AST | | 39.505127,-107.931594 |
| Comment: <input type="text"/> | | | | | |
| Corrective Action: <input type="text"/> | | | | | Date: <input type="text"/> |

PaintCondition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

| | | | | | |
|--------------------|---------------------|---------------------|---------------------|-------------|--------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | , |
| Comment: | Centralized battery | | | | |

| | | | |
|--------------------|----------|---------------------|---------------------|
| Corrective Action: | | Date: | |
| Paint | | | |
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |
| Berms | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) |
| | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | |
|-----------------------|--------------|-----------------------|-----------------------------|
| Facility ID: 276956 | Type: WELL | API Number: 045-10575 | Status: PR Insp. Status: PR |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |
| | | | |
| Facility ID: 276958 | Type: WELL | API Number: 045-10574 | Status: PR Insp. Status: PR |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |
| | | | |
| Facility ID: 276961 | Type: WELL | API Number: 045-10573 | Status: PR Insp. Status: PR |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |

| Environmental | |
|-----------------------------------|--------------------------------------------------|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): NO | |
| Comment: | |
| Pilot: | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | | | | | |
| Drains | Pass | | | | | |
| | | Gravel | Pass | | | |
| Seeding | Pass | | | | | |
| | | Ditches | Pass | | | |
| Rip Rap | Pass | | | | | |
| | | Culverts | Pass | | | |
| Sediment Traps | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401253641 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118766 |