

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2017

Submitted Date:

04/07/2017

Document Number:

674901607

### FIELD INSPECTION FORM

Loc ID 326403 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 77330  
 Name of Operator: SG INTERESTS I LTD  
 Address: 100 WAUGH DR SUITE 400  
 City: HOUSTON State: TX Zip: 77007

**Findings:**

- 4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspections@sginterests.com	<a href="#">All Inspections</a>
Fischer, Alex		alex.fischer@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105413	PIT		09/23/1999		-	UTE 33-8-5 2	

**General Comment:**

On March 30, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #105413. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #105413 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: 105413      Lat: 37.127559      Long: -107.734284

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: [Location inspection conducted to determine physical existence of pit facility ID #105413.](#)

Corrective Action

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">On March 30, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #105413. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #105413 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.</a>	hughesj	04/07/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401253664	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118784">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118784</a>
674901608	Ute 33-8-5 #2 location photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118783">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118783</a>