

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2017

Submitted Date:

04/11/2017

Document Number:

666803103

### FIELD INSPECTION FORM

Loc ID 334603 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
 Name of Operator: ENCANA OIL & GAS (USA) INC  
 Address: 370 17TH ST STE 1700  
 City: DENVER State: CO Zip: 80202-

**Findings:**

- 5 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256965	WELL	PR	09/15/2014	GW	045-07504	SHAEFFER 11-1 (D12)	TA
256966	WELL	PR	06/01/2002	GW	045-07505	SHAEFFER 12-3 (D12)	PR
256967	WELL	PR	11/22/2005	GW	045-07506	SHAEFFER 12-5 (D12)	PR

**General Comment:**

[Shared tank battery with location ID 334680](#)



Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 256965 Type: WELL API Number: 045-07504 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current form 4 on file to continue Temporarily Abandoned well

Corrective Action: Contact COGCC engineering staff Date: 04/25/2017

Facility ID: 256966 Type: WELL API Number: 045-07505 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 256967 Type: WELL API Number: 045-07506 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					
Berms	Pass					
Ditches	Pass					
Seeding	Pass					
Sediment Traps	Pass					
		Culverts	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401256557	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121509</a>