

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2017

Submitted Date:

04/20/2017

Document Number:

685302630**FIELD INSPECTION FORM**
 Loc ID 326573 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258189	WELL	PR	05/09/2000	GW	067-08333	FEDERAL LAND BANK A 2	PR

General Comment:

See link at end of report for path to downloadable pictures. Inspection report contains corrective action and comment. See Signs/Marker and Tanks and Berms sections of report for additional details.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign is peeling and required information is unreadable.		
Corrective Action:	Install sign to comply with Rule210.b.	Date:	06/20/2017

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	Corrective action completed.	
Corrective Action:		Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	21 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Weeds and grass are growing inside containment.			
Corrective Action:	Remove graas and weeds to comply with Rule 605.a.(4).			Date: 05/21/2017

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	258189	Type:	WELL	API Number:	067-08333	Status:	PR	Insp. Status:	PR

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Rip Rap	Pass					
Gravel	Pass					
Check Dams	Pass	Culverts	Pass			
Sediment Traps	Pass					
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Containment ring around produced water tank.
Compaction	Pass	Gravel	Pass			

Comment: [Corrective action completed.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302706	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128689
685302707	Production equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128690
685302708	Wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128691
685302709	Produced water tank with grass growing inside containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128692
685302710	Erosion channel repair.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128693