

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/24/2017

Document Number:

674901616**FIELD INSPECTION FORM**

Loc ID 311927 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	WPX Inspection Mailbox

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105513	PIT				-	BONDAD 33-9 19A	EI
214646	WELL	PA	04/16/2008	GW	067-06250	BONDAD 33-9 19A	EI
295729	PIT				-	BONDAD 33-9 #19A	EI

General Comment:

On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #19A location. For the most recent field inspection report of this facility, please refer to document #200219065. The purpose of this location visit was to determine the physical status of Pit Facility ID #295729 and #105513.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	PA Marker.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>105513</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u></u>	Insp. Status: <u>EI</u>
----------------------------	------------------	----------------------	-----------------	-------------------------

Facility ID: <u>214646</u>	Type: <u>WELL</u>	API Number: <u>067-06250</u>	Status: <u>PA</u>	Insp. Status: <u>EI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>295729</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u></u>	Insp. Status: <u>EI</u>
----------------------------	------------------	----------------------	-----------------	-------------------------

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PITType: PluggingLined: YESPit ID: 295729Lat: 37.115450Long: -107.780900

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

[Pit Facility ID #295729 currently has an unknown status in the COGIS database.](#)

Corrective Action

[Contact COGCC EPS staff for directives per Rule 905.b.](#)Date: 05/05/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Type: Evaporation

Lined:

Pit ID: 105513Lat: 37.116469Long: -107.779865

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

[Pit Facility ID #105513 currently has an unknown status in the COGIS database.](#)

Corrective Action

[Contact COGCC EPS staff for directives per Rule 905.b.](#)Date: 05/05/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:				Date:
Corrective Action				
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:		Date:
Comment:				
Corrective Action				
Permit:	Facility ID	Permit Num	Expiration Date	
	295729	1733166		
	295729	1733166		

COGCC Comments

Comment	User	Date
On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #19A location. For the most recent field inspection report of this facility, please refer to document #200219065. The purpose of this location visit was to determine the physical status of Pit Facility ID #295729 and #105513. No open pits were observed during this field inspection.	hughesj	04/24/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901617	Bondad 33-9 #19A PA marker.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130697