



**photo 1:** Facing east at the beginning of the access road.



**photo 2:** Facing southeast along the access road.





**photo 3:** There are minor signs of erosion at this area along the access road.



**photo 4:** Sediment is being deposited at the rock rip/rap.





**photo 5:** Facing southeast along the access road.



**photo 6:** Facing southeast toward the Julieanna pit at the location.





**photo 7:** Rock rip/rap is installed where stormwater is directed towards the pit.



**photo 5:** Facing northeast toward the pit.





**photo 9:** There is noxious weeds (Musk thistle) beginning to germinate in areas around the pit.



**photo 10:** Facing northwest toward the pit.





**photo 11:** Facing north toward the location along the east fill slope.



**photo 12:** Facing northwest toward the location.





**photo 13:** Northeast side of the location facing southwest.



**photo 14:** Facing west toward the cut slope.