



photo 1: Facing northeast at the beginning of the access road.



photo 2: Facing northeast along the access road.



photo 3: Facing northeast along the access road.



photo 4: The water bar diverts stormwater toward the rock rip/rap. There is scouring beginning to occur at this point.



photo 5: Facing northeast along the access road.



photo 6: Facing northeast along the access road toward the location.



photo 7: Facing northeast toward the location.



photo 8: Facing southwest toward the location and access road.