



photo 1: Facing south toward the location off of the main access road.



photo 2: Facing south along the east fill slope of the location.



photo 3: Facing southwest at the location.



photo 4: Facing northwest at the location.



photo 5: South side of the reclaimed pit area facing north.



photo 6: Southeast side of the pit area facing northwest.



photo 7: North site of the offsite pit area facing south.



photo 8: Facing southeast toward the reclaimed pit area.



photo 9: Noticed a thistle beginning to germinate at the reclaimed area as well as at the location.



photo 10: There is solid color baling twine noticed at the location which may indicate that the straw mulch was not certified weed free.