



photo 1: Facing east toward at the beginning of the access road.



photo 2: Facing east along the access road. Some of the vehicle tracks turn to the right around the location.



photo 3: Facing east toward the location.



photo 4: Facing northeast at the location. Vehicle tracks appear to turn around on location.



photo 5: Facing east along the north fill slope.



photo 6: Northeast side of the location facing southwest.



photo 7: The stormwater is directed to this point at the east side of the location. Sediment is accumulating in front of the rock rip-rap.



photo 8: East side of the location facing west.