



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the western portion of the project area from the southwestern corner facing northward. Vegetation is largely weeds such as cranesbill (*Erodium cicutarium*). It does not appear that the interim reclamation area was ever seeded.



Photo 3: View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4: View of musk thistles (*Carduus nutans*) within the interim reclamation area.



Photo 5: Another view of musk thistles within the interim reclamation area.