

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2017

Submitted Date:

04/21/2017

Document Number:

674901609**FIELD INSPECTION FORM**
 Loc ID 325163 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@elmridge.net	
Lindeman, Terry	(505) 632-3476 Ext 210	tlindeman@elmridge.net	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214173	WELL	PR	11/14/1957	GW	067-05493	FASSETT MESAVERDE UNIT 1	EI

General Comment:

On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Fassett Mesaverde #1. For the most recent field inspection report for this facility, please refer to document #674901469. Corrective actions required by that document have been completed.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	PW vessel is labeled with contents, volume, and NFPA placard.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.122900,-107.762789
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 20 bbl.

Other (Type)

Berms

Inspector Name: Hughes, Jim

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Secondary containment berm has been rebuilt with adequate capacity.				
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214173	Type:	WELL	API Number:	067-05493	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/> Corrective Action: <input type="text"/>						Date: <input type="text"/>
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
<p>On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Fassett Mesaverde #1. For the most recent field inspection report for this facility, please refer to document #674901469. Corrective actions required by that document have been completed.</p> <p>The secondary containment berm around the produced water tank has been rebuilt with adequate capacity.</p> <p>The location has been bladed.</p>	hughesj	04/21/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401264840	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129233
674901610	Fassett MV #1 production equipment and well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129206
674901611	Location has been bladed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129207
674901612	Secondary containment berm has been rebuilt.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129208