

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/24/2017

Document Number:

674901616**FIELD INSPECTION FORM**

Loc ID 311927 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	<a href="#">WPX Inspection Mailbox</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105513	PIT				-	BONDAD 33-9 19A	EI
214646	WELL	PA	04/16/2008	GW	067-06250	BONDAD 33-9 19A	EI
295729	PIT				-	BONDAD 33-9 #19A	EI

**General Comment:**

On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #19A location. For the most recent field inspection report of this facility, please refer to document #200219065. The purpose of this location visit was to determine the physical status of Pit Facility ID #295729 and #105513.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	PA Marker.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:  Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities							
Facility ID:	<u>105513</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status: <u>          </u>	Insp. Status: <u>EI</u>
Facility ID:	<u>214646</u>	Type:	<u>WELL</u>	API Number:	<u>067-06250</u>	Status: <u>PA</u>	Insp. Status: <u>EI</u>
Facility ID:	<u>295729</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status: <u>          </u>	Insp. Status: <u>EI</u>

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType: PluggingLined: YESPit ID: 295729Lat: 37.115450Long: -107.780900Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Pit Facility ID #295729 currently has an unknown status in the COGIS database.

Corrective Action

Contact COGCC EPS staff for directives per Rule 905.b.Date: 05/05/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment: 

Corrective Action

Date: **Netting:**

Netting Type:

Netting Condition:

Comment: 

Corrective Action

Date: 

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment: 

Corrective Action

Date: Type: Evaporation

Lined:

Pit ID: 105513Lat: 37.116469Long: -107.779865Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Pit Facility ID #105513 currently has an unknown status in the COGIS database.

Corrective Action

Contact COGCC EPS staff for directives per Rule 905.b.Date: 05/05/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment: 

Corrective Action

Date: **Netting:**

Netting Type:

Netting Condition:

Inspector Name: Hughes, Jim

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		
Corrective Action		
		Date:

**COGCC Comments**

Comment	User	Date
On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #19A location. For the most recent field inspection report of this facility, please refer to document #200219065. The purpose of this location visit was to determine the physical status of Pit Facility ID #295729 and #105513. No open pits were observed during this field inspection.	hughesj	04/24/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401266378	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130856</a>
674901617	Bondad 33-9 #19A PA marker.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130697</a>