

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/24/2017

Document Number:

674901622

FIELD INSPECTION FORM

Loc ID 325153 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96705
 Name of Operator: WPX ENERGY PRODUCTION LLC
 Address: P O BOX 3102 MS-25-2
 City: TULSA State: OK Zip: 74101

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	WPX Inspection Mailbox

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214144	WELL	PA	06/28/2012	GW	067-05459	BONDAD 33-9 19	EI

General Comment:

On April 20, 2017 COGCC SE EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #19. For the most recent field inspection report of this facility, please refer to document #680600797. The purpose of this site visit was to document the physical status of Pit Facility ID #105512.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	No PA marker observed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214144 Type: WELL API Number: 067-05459 Status: PA Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 105512 Lat: 37.112749 Long: -107.770825

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Pit Facility ID #105512 currently has an unknown status in the COGIS database..

Corrective Action: Contact COGCC EPS staff for directives per Rule 905.b.

Date: 05/05/2017c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
<p>On April 20, 2017 COGCC SE EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #19. For the most recent field inspection report of this facility, please refer to document #680600797. The purpose of this site visit was to document the physical status of Pit Facility ID #105512.</p> <p>During this field inspection it was noted that: There is no surface indication of a pit on this location. A PA marker was not observed during this inspection. Several bare areas exist on location. Upon further review of historical aerial images, production equipment was located where these areas are. Contact SW Regional Reclamation Specialist to address areas devoid of vegetation.</p>	hughesj	04/24/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401266382	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130858
674901623	Bondad 33-9 #19 Aerial photo showing bare spots.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130701
674901624	Bare spots where production equipment was located.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130702
674901625	Bare/weed filled area where equipment was located.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130703