

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/24/2017

Document Number:

674901629

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325145 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96705
 Name of Operator: WPX ENERGY PRODUCTION LLC
 Address: P O BOX 3102 MS-25-2
 City: TULSA State: OK Zip: 74101

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	WPX Inspection Mailbox
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214120	WELL	PR	01/27/1956	GW	067-05430	BONDAD 33-9 7	EI

General Comment:

On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #7. For the most recent field inspection report of this facility, please refer to document #674600370.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Location sign mounted to fencing for open topped PW PBV.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: Yes

Comment: Lube oil leak onto compressor skid.

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Post and wire fencing around perimeter of secondary containment berm.		
Corrective Action:		Date:	

Equipment:

Type	Area	Volume	corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical injection system.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Lube oil leak onto compressor skid.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Telemetry.			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.106585,-107.782179
Comment:	Expanded metal cover.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	125 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214120 Type: WELL API Number: 067-05430 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: Chemical injection system and lube oil containers have secondary containment.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Bondad 33-9 #7. For the most recent field inspection report of this facility, please refer to document #674600370. The skid mounted compressor has a lube oil leak.	hughesj	04/24/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401266385	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130860
674901630	125 bbl. PW PBV and other production equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130706
674901631	Skid mounted compressor with lube oil leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130707