

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2017

Submitted Date:

05/01/2017

Document Number:

674005161

FIELD INSPECTION FORM

Loc ID 319066 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKWOOD State: CO Zip: 80235

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Herring, Debora		toporting@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242823	WELL	PR	11/28/2011	OW	123-10614	RUNYAN 1	PR
431772	WELL	PR	02/03/2014	OW	123-36766	Runyan 3	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	IGNITOR/COMBUSTOR		
Comment:	Pipe		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barb Wire		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 2		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST			
Comment:						
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities		
Facility ID: <u>242823</u>	Type: <u>WELL</u>	API Number: <u>123-10614</u>
Status: <u>PR</u>	Insp. Status: <u>PR</u>	
Producing Well		
Comment: <u>PR</u>		
Corrective Action:		Date:
BradenHead		
Comment: <u>Bradenhead plumbed to surface.</u>		
Corrective Action:		Date: _____
Facility ID: <u>431772</u>	Type: <u>WELL</u>	API Number: <u>123-36766</u>
Status: <u>PR</u>	Insp. Status: <u>PR</u>	
Producing Well		
Comment: <u>PR</u>		
Corrective Action:		Date:
BradenHead		
Comment: <u>Bradenhead plumbed to surface.</u>		
Corrective Action:		Date: _____
COGCC Comments		
Comment	User	Date
<u>Routine inspection.</u>	carlilec	05/01/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674005162	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4136445