

Inspection Photos
Location Name: Mahoney #1
API: 05-123-08110



Photo from prior inspection for comparison purposes



Photo 1: Stained soil at compressor removed

Inspection Photos
Location Name: Mahoney #1
API: 05-123-08110



Photo from prior inspection for comparison purposes



Photo 2: Stained soil in separator house

Inspection Photos
Location Name: Mahoney #1
API: 05-123-08110



Photo from prior inspection for comparison purposes



Photo 3: Stained soil at wellhead, bradenhead not plumbed to surface.

Inspection Photos
Location Name: Mahoney #1
API: 05-123-08110



Photo from prior inspection for comparison purposes



Photo 4: Weeds at meter controlled