

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2017

Submitted Date:

04/27/2017

Document Number:

666803129

FIELD INSPECTION FORM

Loc ID 335438 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

- 9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277907	WELL	PR	03/11/2006	GW	045-10805	SILT VALLEY 34C-22-692	PR
277909	WELL	PR	03/05/2006	GW	045-10806	SILT VALLEY 34A-22-692	PR
277910	WELL	PR	03/05/2006	GW	045-10807	SILT VALLEY 44A-22-692	PR
278947	WELL	PR	03/13/2006	GW	045-10967	SILT VALLEY 44C-22-692	PR

General Comment:

[Inspection is for odor complaint in area](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Vertical Separator	# 0				
Horizontal Heated Separator	# 4				
Plunger Lift	# 4				
Emission Control Device	# 1				
Ancillary equipment	# 1	Chemical unit at wellhead			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	200 BBLs	STEEL AST		39.508591,-107.647583
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>277907</u>	Type:	<u>WELL</u>	API Number:	<u>045-10805</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>277909</u>	Type:	<u>WELL</u>	API Number:	<u>045-10806</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>277910</u>	Type:	<u>WELL</u>	API Number:	<u>045-10807</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>278947</u>	Type:	<u>WELL</u>	API Number:	<u>045-10967</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Seeding	Pass					
		Culverts	Pass			
		Compaction	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401268625	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4133351