

Reclamation and Stormwater Inspection

May 2, 2017

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 440224

Weld County, CO

SENE Section 14 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURROUGHS SOUTH SENE /PAD #1

Location ID: 440224



Photo 1. Photo taken from the eastern perimeter of the location, facing South. Ditch and berm BMP has been installed around most of the location in conjunction with other BMPs and appears to be properly functioning.



Photo 2. Photo taken from the southern perimeter of the location, facing West. Oil and gas locations are to be kept free of supplies. Appears supplies are being stored along the southern location, some of which have been placed along the BMP area.

Inspection Photos
Location Name: BURROUGHS SOUTH SENE /PAD #1
Location ID: 440224



Photo 3. Photo taken from the southwestern perimeter of the location, facing West. Minor rill erosion along the fill slope. BMPs are in place to capture sediment laden storm runoff from leaving location.



Photo 4. Photo taken from the southwest perimeter of the location, facing Southeast. Sediment trap has been installed with both inlet and outlet protection, as well as check dams.

Inspection Photos
Location Name: BURROUGHS SOUTH SENE /PAD #1
Location ID: 440224



Photo 5. Photo taken from the southwestern perimeter of the location, facing North. Ditch and berm BMP has been installed in conjunction with check dams prior to the sediment trap.



Photo 6. Photo taken from the western perimeter of the location, facing North. Ditch and berm BMP has been installed around the topsoil stockpile. Topsoil has been salvaged, stored and temporarily stabilized along the western perimeter of the location.

Inspection Photos
Location Name: BURROUGHS SOUTH SENE /PAD #1
Location ID: 440224



Photo 7. Photo taken from the northwest perimeter of the location, facing East. Ditch and berm BMP has been installed along portions of the northern perimeter of the location.



Photo 8. Photo taken from the northeastern perimeter of the location, facing West. No stormwater BMP observed. Operators do need to control run-on onto location to minimize erosion and site degradation which may require stormwater BMPs.