



photo 1: Facing toward the production equipment.



photo 2: There is a slow dripping water leak coming out of the wellhead.



photo 3: Facing toward the west side of the location..



photo 4: Well signs.



photo 5: There is a metal shed which is in the arroyo adjacent to the site.



photo 6: Damaged metal shed in the arroyo adjacent to the location.