

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2017

Submitted Date:

05/01/2017

Document Number:

674005157**FIELD INSPECTION FORM**Loc ID 318870 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10542Name of Operator: CUB CREEK ENERGYAddress: 200 PLAZA DRIVE SUITE 100City: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Cub Creek		paul.gottlob@lptenergyservice.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445614	WELL	DG	03/25/2017		123-43128	Haley 9HZ	DG
445615	WELL	DG	04/13/2017		123-43129	Haley 6HZ	DG
445617	WELL	DG	04/15/2017		123-43131	Haley 2HZ	DG
445618	WELL	DG	04/14/2017		123-43132	Haley 4HZ	DG
445620	WELL	DG	03/25/2017		123-43134	Haley 10HZ	DG
445621	WELL	DG	03/24/2017		123-43135	Haley 8HZ	DG
445622	WELL	DG	04/16/2017		123-43136	Haley 3HZ	DG

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Location entrance, See photos		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound wall surrounding location.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>445614</u>	Type: <u>WELL</u>	API Number: <u>123-43128</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>445615</u>	Type: <u>WELL</u>	API Number: <u>123-43129</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>445617</u>	Type: <u>WELL</u>	API Number: <u>123-43131</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>445618</u>	Type: <u>WELL</u>	API Number: <u>123-43132</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>445620</u>	Type: <u>WELL</u>	API Number: <u>123-43134</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>445621</u>	Type: <u>WELL</u>	API Number: <u>123-43135</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>445622</u>	Type: <u>WELL</u>	API Number: <u>123-43136</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

COGCC Comments

Comment	User	Date
Drilling inspection. Company representative on location: Siji Chaparro	carlilec	05/01/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401271416	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4136384
674005158	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4136378