

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2017

Submitted Date:

05/02/2017

Document Number:

666803151

**FIELD INSPECTION FORM**

Loc ID 311545 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210732	WELL	PR	03/14/1986	GW	045-06490	DOE 1-M-19	PR
210900	WELL	PR		GW	045-06658	DOE 1-W-19	PR

**General Comment:**

[Shared tank battery with location ID 335448](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1				
Type: Gas Meter Run	# 1				
Type: Horizontal Heated Separator	# 1				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		

Comment: Centralized battery

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:

Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		

Comment: Centralized battery

Corrective Action:						Date:			
<b>Paint</b>									
Condition		Adequate							
Other (Content)									
Other (Capacity)									
Other (Type)									
<b>Berms</b>									
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:									
Corrective Action:						Date:			
Contents		#	Capacity	Type		Tank ID	SE GPS		
PRODUCED WATER		2	300 BBLs	STEEL AST					
Comment: Centralized battery									
Corrective Action:						Date:			
<b>Paint</b>									
Condition		Adequate							
Other (Content)									
Other (Capacity)									
Other (Type)									
<b>Berms</b>									
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:									
Corrective Action:						Date:			
Contents		#	Capacity	Type		Tank ID	SE GPS		
CONDENSATE		2	400 BBLs	STEEL AST			39.514727,-107.925985		
Comment:									
Corrective Action:						Date:			
<b>Paint</b>									
Condition		Adequate							
Other (Content)									
Other (Capacity)									
Other (Type)									
<b>Berms</b>									
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Metal		Adequate		Walls Sufficient		Base Sufficient		Adequate	
Comment:									
Corrective Action:						Date:			
<b>Venting:</b>									

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 210732 Type: WELL API Number: 045-06490 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 210900 Type: WELL API Number: 045-06658 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Rip Rap	Pass					
Ditches	Pass					
		Ditches	Pass			
		Gravel	Pass			
Sediment Traps	Pass					
Berms	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401273007	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4137642">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4137642</a>