



photo 1: There is erosion occurring along the access road and rock check dams have filled in with sediment.



photo 2: Facing back toward the west. The culvert along the access road is filling in with sediment.



photo 3: The dripping water leak at the east wellhead has been reduced.




photo 4: The wellhead at the west side of the location is now leaking water.