

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2017

Submitted Date:

05/03/2017

Document Number:

679700436**FIELD INSPECTION FORM**

Loc ID 307060 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10312Name of Operator: PROSPECT ENERGY LLCAddress: 880 WOLVERINE COURTCity: CASTLE ROCK State: CO Zip: 80108**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Cameron Gracey		graceyservices@msn.com	Gracey Services
Ward Giltner		w.giltner@grynberg.com	Prospect Energy
Meghan		mtwele@progressivepcs.net	Progressive Services
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216716	WELL	PR	09/20/2006	OW	069-05129	COMMUNITY (MUDDY UNIT) 1	EI
450192	SPILL OR RELEASE	AC			-	Community (Muddy Unit) 1	EI

General Comment:

Inspected Facilities									
Facility ID:	<u>216716</u>	Type:	<u>WELL</u>	API Number:	<u>069-05129</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>450192</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

--

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment	Temporary stockpile on location pending disposal profile from landfill			
Corrective Action				Date: _____

Spill/Remediation:

Comment: [Impacted surface soils have been excavated and are pending disposal. Well is shut-in pending workover rig availability to repair tubing and sucker rods. Operator's consultant was on location and collected confirmation soil samples. Operator will submit further information regarding spill remediation on Supplemental Form 19.](#)

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401274267	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138592