

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2017

Submitted Date:

05/05/2017

Document Number:

674901642**FIELD INSPECTION FORM**

Loc ID 325308 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name           | Phone | Email                      | Comment |
|------------------------|-------|----------------------------|---------|
| Fischer, Alex          |       | alex.fischer@state.co.us   |         |
| St John, William (Cal) |       | cal.stjohn@state.co.us     |         |
| Adamczyk, Megan        |       | megan.adamczyk@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214536      | WELL | PR     | 08/01/2013  | GW         | 067-06139 | CUSHING C-1   | EI          |

**General Comment:**

On May 5, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings Cushing C-1. This site visit was in response to a complaint filed by the landowner. The complaint (Document #200442372) reported that two pipe stubs located where the ASTs were have no caps on them and that oil had leaked onto the ground. For the most recent field inspection report for this location, please refer to document #685301210.

**Location**Overall Good: ☐

|                      |                                    |       |  |
|----------------------|------------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                    |       |  |
| Type                 | WELLHEAD                           |       |  |
| Comment:             | Sign propped up against well head. |       |  |
| Corrective Action:   |                                    | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

Overall Good: ☐

|                    |                                                                                                                                                              |          |  |                  |
|--------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|--|------------------|
| <b>Spills:</b>     |                                                                                                                                                              |          |  |                  |
| Type               | Area                                                                                                                                                         | Volume   |  |                  |
| Crude Oil          | Tank                                                                                                                                                         | <= 1 bbl |  |                  |
| Comment:           | 2" pipe stubs near historic tank battery location are stained and wet with oil. An approximately 4' diameter area surrounding the pipes is stained with oil. |          |  |                  |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.                                                                    |          |  | Date: 05/05/2017 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 214536 | Type: | WELL | API Number: | 067-06139 | Status: | PR | Insp. Status: | EI |

|  |
|--|
|  |
|--|

## Environmental

### Spills/Releases:

|                                   |                               |
|-----------------------------------|-------------------------------|
| Type of Spill: _____              | Estimated Spill Volume: _____ |
| Comment: _____                    |                               |
| Corrective Action: _____          | Date: _____                   |
| Reportable: _____                 | GPS: Lat _____ Long _____     |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____  |

### Water Well Complaint:

|                        |                   |             |       |
|------------------------|-------------------|-------------|-------|
|                        |                   | Lat         | Long  |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | _____ |

### Field Parameters:

|  |
|--|
|  |
|--|

|                        |                |
|------------------------|----------------|
| Sample Location: _____ | Comment: _____ |
|------------------------|----------------|

**Reclamation - Storm Water - Pit****Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:  Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | User    | Date       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|------------|
| <p>On May 5, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings Cushing C-1. This site visit was in response to a complaint filed by the landowner. The complaint (Document #200442372) reported that two pipe stubs located where the ASTs were have no caps on them and that oil had leaked onto the ground. For the most recent field inspection report for this location, please refer to document #685301210.</p> <p>The flow lines from the well head to the historic tank battery at this location were found uncapped with impacted material surrounding them. COGCC staff reinstalled one of the caps that had been left unscrewed and installed a bull plug in the other 2" line. This bull plug was labeled "COGCC" and "Do Not Remove". Fresh oil was observed on and around the pipe stubs. No recent evidence of activity at or near these pipe stubs or the well head itself were observed.</p> <p>The access road to the well head has a locked gate. Tire tracks were observed traveling over the fence adjacent to the gate. All of the valves at the well head are in the closed position and there is no indication of tampering. As a safety precaution, a rubber hose coming off of the drop out tank was routed into an orifice on the drop out tank.</p> | hughesj | 05/05/2017 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                                  | URL                                                                                                                                                                 |
|--------------|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401276165    | INSPECTION SUBMITTED                                         | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140770">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140770</a> |
| 674901643    | Area where historic tank battery was located.                | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140763</a> |
| 674901644    | Impacted material around pipe stubs.                         | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140764">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140764</a> |
| 674901645    | Uncapped pipe stubs and impacted material.                   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140765">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140765</a> |
| 674901646    | Pipe stubs with caps installed by SW EPS.                    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140766">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140766</a> |
| 674901647    | Access road with locked gate and traffic pattern over fence. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140767">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140767</a> |
| 674901648    | Both pipe stubs were capped during this inspection.          | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140768">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140768</a> |
| 674901649    | Cushing C-1 well head.                                       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140769">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140769</a> |