

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2017

Submitted Date:

05/05/2017

Document Number:

679902516**FIELD INSPECTION FORM**

Loc ID 321791 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------|---------------------------|---------|
| Smalley, Carl | 719-767-8805 | csmalley@mulldrilling.com | |
| Akers, Tracy | 719-342-1813 | takers@mulldrilling.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 208028 | WELL | TA | 01/01/1995 | SI | 017-06963 | NWAU 26 | TA |

General Comment:

Location**Lease Road:**

| | | | |
|-------------------|-------------------------------|-------|--|
| Type | Access | | |
| comment: | Dirt road through farm ground | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Lease sign by wellhead | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 208028 Type: WELL API Number: 017-06963 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: PEAK WIRELINE RIH W/CIBP SET @ 5265' 3/17/17. 2 SX CMT ON TOP OF CIBP
4/10/17. MIT 5/2/17. MIRU PROSTIM. LOAD CSG W/2BBL. PRESSURED UP TO 470
PSI. PRESSURE AFTER 10 MIN WAS 390 PSI. FAILED

Corrective Action: CONTACT COGCC ENGINEERING FOR DIRECTIVES WITHIN 10 DAYS OF RECEIPT
OF THIS INSPECTION

Date: 05/12/2017

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401276127 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140740 |
| 679902528 | Form 21 5/2/17 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4140731 |