



photo 1: Facing northeast along the main access road. There is vehicle rutting and potholes in this area of the road.



photo 2: Facing southwest toward the location.



photo 3: Facing south along the main road which goes thru the location. There is vehicle rutting and potholes in this area of the road.



photo 4: Facing southwest toward the cut slope of the location.