



photo 1: Facing northeast along the main access road. There is vehicle rutting in this area of the road.



photo 2: There are signs of erosion in areas of the main road.



photo 3: Facing south toward the access road.



photo 4: Stormwater from the above photo is causing erosion across the main road.



photo 5: Facing south toward the location.



photo 6: East side of the location facing north.