



photo 1: Facing southwest along the access road. This portion of the access road has signs of vehicle rutting .



photo 2: Facing toward the location.