

# Construction and Stormwater Inspection

May 5 & 11, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 336284

Weld County, CO

NWNW Section 8 T1N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: FL GREENS FEDERAL /35N-8HZ

Location ID: 336284



Google Earth aerial imagery taken October 9, 2015 of the location overlaid with field collected data using a Trimble handheld GPS. Field collected data on May 5, 2017 using a Trimble handheld GPS would indicate construction disturbance totaled 10.26 acres. Aerial imagery also illustrates the location and a potentially active Swainson's hawk nest observed during the inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 682402104

Inspection Photos  
Location Name: FL GREENS FEDERAL /35N-8HZ  
Location ID: 336284



**Photo 1.** Photo taken May 5, 2017 from the northern location, facing East. A ditch and berm BMP has been installed around the perimeter of the location.



**Photo 2.** Photo taken May 5, 2017 from the northeastern location, facing South. A ditch and berm BMP has been installed around the perimeter of the location.



**Inspection Photos**  
**Location Name: FL GREENS FEDERAL /35N-8HZ**  
**Location ID: 336284**



**Photo 3.** Photo taken May 5, 2017 from the eastern location, facing South. A ditch and berm BMP has been installed around the perimeter of the location. During the May 5, 2017 inspection, berm material did not appear consistently compacted throughout the location. Berm BMPs appeared to be further compacted during the May 11, 2017 inspection.



**Photo 4.** Photo taken May 5, 2017 from the eastern location, facing South. A ditch and berm BMP has been installed around the perimeter of the location. During the May 5, 2017 inspection, berm material did not appear consistently compacted throughout the location. Berm BMPs appeared to be further compacted during the May 11, 2017 inspection.

**Inspection Photos**  
**Location Name: FL GREENS FEDERAL /35N-8HZ**  
**Location ID: 336284**



**Photo 5.** Photo taken May 5, 2017 from the southeastern location, facing West. A ditch and berm BMP has been installed around the perimeter of the location. During the May 5, 2017 inspection, berm material did not appear consistently compacted throughout the location. Berm BMPs appeared to be further compacted during the May 11, 2017 inspection.



**Photo 6.** Photo taken May 5, 2017 from the southern location, facing West. A ditch and berm BMP has been installed around the perimeter of the location.



Inspection Photos  
Location Name: FL GREENS FEDERAL /35N-8HZ  
Location ID: 336284



**Photo 7.** Photo taken May 5, 2017 from the western location, facing North. A ditch and berm BMP has been installed around the perimeter of the location. Topsoil stockpile has been salvaged and stored along the western location. Topsoil side slopes appear steep and may be difficult to stabilize.



**Photo 8.** Photo taken May 5, 2017 from the northwestern location, facing East. A ditch and berm BMP has been installed around the perimeter of the location.

Inspection Photos  
Location Name: FL GREENS FEDERAL /35N-8HZ  
Location ID: 336284



**Photo 9.** Photo taken May 5, 2017 from the northern location, facing South. A ditch and berm BMP has been installed around the perimeter of the location.



**Photo 10.** Photo taken May 5, 2017 from the northern location, facing South. Fugitive dust was evident during operations. COGCC contacted the Operator and the Operator communicated to COGCC that there was a water at location.



Inspection Photos  
Location Name: FL GREENS FEDERAL /35N-8HZ  
Location ID: 336284



**Photo 11.** Photo taken May 11, 2017 from the northwest location, facing North. A sediment trap has been installed with both outlet protection devices. Portions of the sediment trap berm do not appear consistently compacted.



**Photo 12.** Photo taken May 11, 2017 from the southwest location, facing Southwest. A sediment trap has been installed with both outlet protection devices. Portions of the sediment trap berm do not appear consistently compacted.



**Inspection Photos**  
**Location Name: FL GREENS FEDERAL /35N-8HZ**  
**Location ID: 336284**



**Photo 13.** Photo taken May 11, 2017 from the entrance of location, facing South. Did not observe a tracking pad. COGCC staff contacted the Operator and the Operator communicated to COGCC staff that tracking pad material was supposed to be installed on that day. The Operator said street sweeping operations were being conducted.



**Photo 14.** Photo taken May 11, 2017, from the entrance of location, facing East. It appears that the Operator has performed street sweeping operations.