

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2017

Submitted Date:

05/08/2017

Document Number:

680301945

FIELD INSPECTION FORM

Loc ID 312138 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------|---------------------------------|
| Pape, Terry | 970-768-5700 | tpape@hrmres.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 218713 | WELL | PR | 04/26/2007 | OW | 075-05445 | FRASCO 1-B | PA |

General Comment:

[P&A Completed SATISFACTORY Remove all equipment and begin reclamation process. Contact COGCC Environmental Group for pit closure directives and COGCC Reclamation Group for reclamation directives.](#)

Location

Lease Road:

| | | | |
|--------------------|---|-------|--|
| Type | Access | | |
| comment: | P&A completed. Begin reclamation process with removal of all equipment and surface preparation. | | |
| Corrective ActionL | | Date: | |

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | P&A completed. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|-------|
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | _____ |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| | | | |
|--------------------|---|-------|-----------------|
| | | | corrective date |
| Type: Other | # 0 | | |
| Comment: | Equipment remains on-site at time/date of this FIR. Remove all equipment and begin reclamation process. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 218713 Type: WELL API Number: 075-05445 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Ranger

Contractor Phone: 713-935-8900

Surface Casing

Cement Volume (sx): 40+100+25

Circulate to Surface: YES

Cement Fall Back:

Top Job, 1" Volume: YES

Intermediate Casing

Cement Volume (sxs):

Good Return During Job:

Production Casing

Cement Volume (sx): 2+50

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 5449 4487 1400 253

Cement Volume (sx): 2+50+40+100+25

Good Return During Job:

Cement Type: 15.8#

Comment: Final Day - SATISFACTORY - Tagged TOC @ 80' from surface, pumped (25) sks to surface. Excavated at wellhead (6) ' below surface, cut and weld cap w/info., backfill. P&A COMPLETED

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | In Process | Other | In Process | | | |

Comment: Continue stormwater erosion management BMP's until final reclamation approval is attained from COGCC.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| P&A Completed - SATISFACTORY - Remove all equipment and begin reclamation process. Contact COGCC Environmental and COGCC Reclamation for directives and approvals. | schureky | 05/08/2017 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401276910 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4141378 |