

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2016

Submitted Date:

04/24/2017

Document Number:

679100025**FIELD INSPECTION FORM**Loc ID 444691 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Nolan Redmon	720-484-2347	nredmond@catamountep.com	

General Comment:

Date of Inspection: 05-26-16

Type of Inspection: Drilling, Containment, Stormwater (Joint Inspection with FIU SW Supervisor)

Location Name: Morales 34-6-6U 1 Pad;

Location ID #: 444691

Construction stormwater BMPs for well pad (perimeter berm, diversion trenches, silt fences, straw wattles, rock check dams, and other spill stormwater control equipment) and access road (borrow ditch with rock check dams for sediment control) are in-place and these stormwater controls indicate no offsite migration of fluids or sediment.

Existing stormwater controls indicate no offsite migration of fluids or sediment to nearby irrigation ditch.

Observed drilling operations of well Morales 34-6-7 #1, API 05-067-09972; drilling operations conducted in accordance with Form 2A COAs; drilling tanks had 3-foot engineered wooden covered with poly containment berms.