

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2017

Submitted Date:

05/09/2017

Document Number:

673715366**FIELD INSPECTION FORM**

Loc ID 442484 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strickler, Robert		Robert.D.Strickler@conocophillips.com	<a href="#">All DJ Basin Inspections</a>
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	<a href="#">All DJ Basin Inspections</a>
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	<a href="#">Regulatory Coordinator</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442485	WELL	XX	07/15/2015	LO	005-07242	Montezuma 4-64 18-13 4H	DG

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Tanks were empty on inspection. Contents, quantity and NFPA will be installed on tanks prior to drilling as discussed.		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:	HP448 sign at 6th, Imboden and site.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	location sign at gate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flare	# 1		
Comment:	emergency flare (see attached photo)		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

### Location Construction

Location ID: 442485 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** Inspector talked with onsite representative about calling the Fire Department and LGD if emergency flaring is needed during drilling. Spill prevention methods were in place on location. Torando shelter on location (see attached photo). Sound wall on north and east sides of location for homes nearby.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:****Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Corrective Action:** \_\_\_\_\_**Date:** \_\_\_\_\_**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**Facility ID: 442485 Type: WELL API Number: 005-07242 Status: XX Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: HP 448 Pusher/Rig Manager: Richard Perez  
Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: Offsite/Fluids&Cuttings

**Comment:** Surface casing new, 9 5/8", 36 wt. Water source from hydrant on Quincy and the gravel pit and Pure Cycle. Drilling scheduled to begin on 5/9/2017/weather permitting.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass	Self Inspection	Pass	
Rip Rap	Pass	Rip Rap	Pass			
Seeding	Pass	Waddles	Pass			
Berms	Pass	Ditches	Pass	Covering Materials	Pass	
Waddles	Pass					
Retention Ponds	Pass	Culverts	Pass	Spill Response	Pass	
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Liner installed under rig \(see attached photo\). Tanks have engineered containment \(see attached photo\).](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401279120	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143347">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143347</a>
673715434	Conoco Montezuma 4-64 18-13 4H	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143338">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143338</a>