

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2017

Submitted Date:

05/09/2017

Document Number:

673715424

FIELD INSPECTION FORM

Loc ID 447874 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10646
Name of Operator: BISON EXPLORATION LLC
Address: PO BOX 1168
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Wenk, Abigal	720-644-6997	awenk@bisonog.com	Regulatory Manager
Akers, John Austin	(303) 550-1877	aakers@bisonog.com	Principal agent
Gonzales, David	720-644-6997	dgonzales@bisonog.com	President and COO

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447895	WELL	PR	02/01/2017		005-07255	Bison 4-64 15-16 2BHZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	at Manila Rd entrance		
Corrective Action:		Date:	
Type	OTHER		
Comment:	at location entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	720-370-5540	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type: Emission Control Device	# 3		corrective date
Comment:	2 pot belly combustors east of frac tanks and one QTI combustor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Temporary tanks, production facility under construction. Located on NW corner of location. On 5/1/2017 Inspector discussed with onsite personnel the need for berm maintenance around frac tanks because of recent storms. By 5/8/2017 the berms were repaired and per onsite representative, it was completed on 5/1/2017 as requested by Inspector. Tanks are also skirted.](#)

Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLs	STEEL AST		,

Comment: _____

Corrective Action: _____ Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: [Same berms as produced water tanks, with skirts.](#)

Corrective Action: _____ Date: _____

Venting:

Yes/No _____

Comment: _____

Corrective Action: _____ Date: _____

Flaring:

Type _____

Comment: _____

Corrective Action: _____ Date: _____

Location Construction

Location ID: 447896 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: Production facilities are under construction, including liner under tanks inside metal berms.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 447895 Type: WELL API Number: 005-07255 Status: PR Insp. Status: PR

Producing Well

Comment: Producing/flowing back into frac tanks. Tank battery is under construction. Feb 2017 reported to COGCC database. Form 5(A)01 is in process, document #401264408, received 4/21/2017.

Corrective Action:

Date:

BradenHead

Comment: On 5/1/2017 BH was 17 psi, casing 175 psi and tubing 720 psi.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Rip Rap	Pass			
Waddles	Pass	Waddles	Pass			
Compaction	Pass	Compaction	Pass			
Berms	Pass	Seeding	Pass			

Comment: [See attached photo of vehicle tracking material at the entrance from Manila Road that requires maintenance soon.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401279127	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143353
673715427	Bison Bison 4-64 15-16 1CHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143346