

Inspection Photos
Location Name: State 6-81-24-4
API: 05-057-06510



Photo 1. View at entrance to location facing west. No interim reclamation apparent. Batter sign on right in foreground is has been knocked off and turned around.

Inspection Photos
Location Name: State 6-81-24-4
API: 05-057-06510



Photo 2. Unconsolidated, pervious berm.



Photo 3. No wildlife protection apparent on exhaust.

Inspection Photos
Location Name: State 6-81-24-4
API: 05-057-06510



Photo 4. Wellhead sign knocked down.



Photo 5. Storage of concrete base and metal container.