

Inspection Photos
Location Name: Fuqua 19-02-10-1H
API: 05-057-06483



Photo 1. View of location at entrance facing south. No interim reclamation apparent.



Photo 2. No wellhead sign.

Inspection Photos
Location Name: Fuqua 19-02-10-1H
API: 05-057-06483



Photo 3. Tanks labeled with multiple contents.



Photo 4. Previous operator on tanks.

Inspection Photos
Location Name: Fuqua 19-02-10-1H
API: 05-057-06483



Photo 5. Equipment stored on location. No interim reclamation apparent.



Photo 6. Dried annual weeds in topsoil pile.