



**photo 1:** Facing north toward the location.



**photo 2:** Facing along west cut slope.





**photo 3:** Facing north at south side of the location.



**photo 4:** Well sign is not appropriately attached.